




K-1812DIV  
1/9

FIG. 1

JC841 U.S. PTO  
09/761584  
01/18/01



**FIG. 2****FIG. 3**

00261584 - 011301

K 78/20 IV  
3/9

FIG. 4




FIG. 5





FIG. 6



K-181205V  
4/9

FIG. 7a




FIG. 7b




FIG. 7c






FIG. 7d




K 78/20 IV  
5/9


**FIG. 8a**



**FIG. 8b**



**FIG. 8c**



00146901-0015345690

K-18120IV  
6/9






FIG. 10a




FIG. 10b




FIG. 10c






FIG. 10d





K781205V  
9/9

FIG. 12a




FIG. 12b




FIG. 12c




FIG. 12d




FIG. 12e




FIG. 12f

